



5846 Hwy 189  
Baker, FL 32531  
850-537-2010

109 Industrial Blvd  
Troy, AL 36079  
334-566-7615

17121 Hwy 231  
Fountain, FL 32438  
850-722-6882

## Valspar Weather X 40 Year Limited Warranty

Within 40 years from the date of application of the paint, Valspar Weather X exhibits cracking, flaking or peeling (loss of adhesion) to an extent that is apparent on ordinary outdoor visual observation. *Minute fracturing, which may occur in proper fabrication of the building parts, is not a covered Warranty Condition. Failure due to substrate corrosion is not a covered Warranty Condition.*

Within 30 years from date of installation of the panels, Valspar Weather X:

1. Chalks in excess of ASTM D-4214-98 method A D659 number six(6) rating on horizontally installed (roofing) panels and a number eight(8) rating on vertically installed (sidewall) panels, when properly maintained as described herein, and
2. Changes color more than seven (7.0) Hunter delta-E units on horizontally installed (roofing) panels and five(5.0) Hunter delta-E units on vertically installed (sidewall) panels as determined by ASTM method D-2244-02. Color change shall be measured on an exposed painted surface that has been cleaned of surface soils and chalk, and the corresponding values measured on the original or unexposed painted surface. Color change may not be uniform on surfaces that are not equally exposed to the sun and elements and Valspar does not warrant color changes will be uniform.

We are not responsible and provide no Warranty benefits, for any damage or condition resulting from circumstances beyond our control, including any of the following:

1. Acts of God, falling objects, explosions, fire, external forces or other such similar or dissimilar circumstances beyond Valspar's control.
2. This limited warranty shall not apply to processed steel panels exposure to harmful fumes, corrosive or aggressive atmospheric conditions, not limited to salt water marine atmospheres or to significant spraying of either salt or fresh water.
3. Weather X which has been damaged due to moisture entrapment in bundles during transit or storage or which has been stored or installed in such a way that allows standing water on the coating.
4. Development of any condition between the coating and the substrate which causes the coating to degrade or delaminate, including any failure or deficiency in the cleaning process or pretreatment.
5. Weather X that has been stored/ installed in such a way that allows contact with animals or animal waste.
6. Mishandling of Weather X or of any substrate coated with it, including abuse, alteration, modification, improper use, or storage.
7. Where materials/ items such as snow guards and solar panels are attached/ adhered to the product.

No Warranty is provided for Valspar Weather X on any substrate that is subjected to sea spray or installed on property located 1,500 or fewer feet from salt-water environment.

All claims will be handled by the Valspar Corporation and the customer will not hold Baker Metal Works & Supply liable for any damage due to the result of a defective panel or the customer's negligence.

### Storage Instructions & Guidelines:

- Store inside a well ventilated, dry location. Do not store outside
- Do not allow moisture to remain between sheet surfaces.
- Break the shipping bands on metal bundle.
- Wipe sheets dry.
- Store metal on end or an incline of at least 8" with support boards underneath to prevent sagging. Fan sheets slightly at the bottom to allow air circulation.
- Keep sheets of metal off the ground in an inclined position with an insulator such as wood.
- Never cover with plastic.
- Moisture between sheets may cause white rust, which can form in as little as 24 hours, and may cause the panel to rust immediately or in several years.
- Direct contact between ACQ or CA treated lumber and metal roofing/ siding panels must be avoided.
- All shavings from screws must be removed in order for rust spots not to form.